

Post Office Box 191 Gardena, California 90247-7638 Telephone: (213) 532-3111

# SERVICE BULLETIN

Classifica EF&EC93-016	Section: Engine Fuel	Models:	All models	
Reference: TECHNICAL BULLETIN NTB93-176		Date:	November 29, 1993	

## **GREEN OR BLUE (TYPE 1M) RELAY CAUTION**


#### SERVICE INFORMATION

When servicing a customer's vehicle, exercise caution when diagnosing / checking at any green or blue colored relay (type1M, 1 make-normally open relay).

#### SERVICE PROCEDURE

When diagnosing at any green or blue colored relay (type1M, 1 make-normally open relay), observe the following cautions to prevent damage to the Engine Control Module (ECM):

1. Note that the schematic on the fuel pump relay is rotated 90 degrees from the orientation of the relay terminals in the relay connector (see diagram below):



2. Exercise caution to ensure that the correct terminals are being probed at the relay connector during diagnosing / checking.

NOTE: If terminals 2 or 3 (battery voltage) are connected to terminal 1, the ECM will become damaged if the circuit being tested has terminal 1 connected to the ECM.

### NISSAN MOTOR CORPORATION U.S.A.

**Technical Publications Department**