

Bulletin No.	TS79-023
Date	April 9, 1979
Classification	CO79-002
Section	Cooling System
Models	All

BLOCK HEATER INSTALLATION

Service Information. When installing engine block heater P/N 99990-00032 or 99990-00033 in Datsun vehicles, a 3/16" diameter "core holder" rod located in the water jacket, may interfere with installing the block heater into the freeze plug hole. If the "core holder" rod interferes with the installation, the rod may be removed or bent as necessary without interfering with engine operation.

