

Bulletin No.	TS83-086
Date	May 27, 1983
Classification	EE83-003
Section	Engine Electrical
Models	All

MOLD LINES ON DISTRIBUTOR CAPS

Service Information

Many distributor caps, both in service and in stock, have fine, visible lines on their interior and exterior surfaces. These are mold lines produced by the bonding of flowed plastic material during the manufacturing process. These mold lines are not cracks and do not cause or contribute to any problems with the ignition system or engine performance.

Do not replace the distributor cap simply because of the presence of mold lines.

