

Bulletin No.	TS79-028
Date	May 10, 1979
Classification	EE79-002
Section	Engine Electrical
Models	All

HITACHI SPARK PLUGS

Service Information. Hitachi Spark Plugs will no longer be available as service parts. The chart below shows the proper NGK spark plug and part number.

Parts Information.

FORMER		NEW		Engine	Vehicle
Hitachi Type	Part No.	NGK Type	Part No.		
L44PW-11	22401-U6804	BP7ES-11	22401-U6817	A14	210 (B310)
L45PW-11	22401-U6805	BP6ES-11	22401-U6816	A15 (210 A/T Wagon)	310 (N10)
L46PW-11	22401-U6806	BP5ES-11	22401-U6815	L20B	510, 200SX
L47PW-11	22401-U6807	BP4ES-11	22401-U6814		620
L44PM-13	22401-H7281	BP7EQ-13	22401-H7288	A14	KHLB310FU
L45PM-13	22401-H7282	BP6EQ-13	22401-H7287		
L46PM-13	22401-H7280	BP5EQ-13	22401-H7285		
L47PM-13	22401-H7283	BP4EQ-13	22401-H7286		
L44W-11	22401-N4704	B7ES-11	22401-N4717	L24E L28E	810 280-ZX
L45W-11	22401-N4705	B6ES-11	22401-N4716		
L46W-11	22401-N4706	B5ES-11	22401-N4715		

Interchangeability: Yes, check service manual for application.