

**Safety Issue Type: Recalls**

**October 09 1980**    NHTSA Campaign Number: 80E026000

**INTERIOR SYSTEMS:SEAT BELTS:LAP:FRONT**

**NHTSA Campaign Number**    80E026000

**Manufacturer**    NSK

**Components**    SEAT BELTS

**Potential Number of Units Affected**    130000

**Summary**

SEAT BELT BUCKLES MAY UNLATCH WHEN SUBJECTED TO FORCES THAT COULD BE PRODUCED IN A VEHICLE CRASH.

**Remedy**

SEAT BELT MANUFACTURER WILL SUPPLY VEHICLE MANUFACTURERS WITH REPLACEMENT BUCKLES TO CORRECT THE DEFECT WITHOUT CHARGE TO OWNER.

**Notes**

VEHICLE CATEGORY: PASSENGER VEHICLES.SYSTEM: INTERIOR; SEAT BELT ASSEMBLIES, BUCKLES, MODEL NOS. 1020 THROUGH 1022.CONSEQUENCES OF DEFECT: FAILURE OF THE SEAT BELT TO ADEQUATELY RESTRAIN THEPASSENGER COULD CAUSE SERIOUS INJURY OR DEATH IN THE EVENT OF A VEHICLEACCIDENT.

**Affected Products (1)**

**Equipment**

BRAND	PART NO.	YEAR
NSK	NSK	9999