

Models	All Models
Section	Body Electrical
Classification	BE86-020
Bulletin No.	TS86-185
Date	October 23, 1986

## RADIO INSTALLATION CAUTION


APPLIED MODELS: All Models

### SERVICE CAUTION

When installing a radio, it is extremely important to use the correct size mounting screws. A screw that is too long will cause internal damage to the radio.

All Nissan radio chassis are marked with a reference code (located near the screw holes) where the last digit indicates the maximum screw length as shown in the example below:

EXAMPLE: M5X8 - 8 indicates a maximum screw length of 8mm.



DO NOT substitute screws without first checking the code to make sure that they do not exceed the maximum length allowed.

BE-48

Index # 004034