

---

Models	All Models
Section	Engine Mechanical
Classification	EM88-004
Bulletin No.	TS88-025
Date	February 22, 1988

## ENGINE BLOCK HEATER

APPLIED MODELS: All models

### SERVICE INFORMATION

Engine antifreeze in more than 50% concentration has been found to adversely affect the life and performance of the engine block heater. High phosphate content in the antifreeze forms a scale around the heating element of the block heater, causing the temperature to rise, with subsequent failure of the seals. Therefore, for best results it is recommended that you use a concentration no greater than 50% antifreeze and 50% water.

---