

NISSAN MOTOR CORPORATION U.S.A.

Post Office Box 191 Gardena, California 90248-0191 Telephone (310) 532-3111

PRODUCT SERVICE INFORMATION

| Reference: Date: PI95-017 September 28, 1995 | | |
|--|----------|--------------------|
| | | |
| | PI95-017 | September 28, 1995 |

GENUINE NISSAN REMANUFACTURED DISTRIBUTOR PROGRAM

APPLIED VEHICLES:

Selected models

SERVICE INFORMATION

Beginning October 2, 1995, Nissan will offer remanufactured distributors for selected Nissan models. Consult the Genuine Nissan Remanufactured Parts Sourcebook for part numbers and affected models. Refer to Parts Bulletin NPB/95-023 for complete program procedures.

SERVICE PROCEDURE

The diagnostic procedure for troubleshooting distributor incidents has not changed. Refer to the appropriate service manual for specific diagnostic procedures.

Index # 044562

Copyright © 1995 NISSAN MOTOR CORPORATION, U.S.A. Technical Communications Department

No part of this bulletin may be reproduced, stored in a retrieval system, or transmitted in any form, or by any means electronic, mechanical, photocopying, recording or otherwise, without the prior written permission of Nissan Motor Corporation U.S.A. Printed in U.S.A.